



IMP RCP PROJECT POSTING TEMPLATE

PROJECT ADMINISTRATORS		
Tim Kinsella	Thomas Mayronne	GID Investment Advisers LLC
(617) 854-9122	(917) 854-9138	125 High St., 27 th Floor
tkinsella@gid.com	tmayronne@gid.com	Boston, MA 02110

Posting Date	5/26/2021	Budgeted Amount	\$102K	GL Account Code	10018
Property Name	Platform 14				
Property Entity Number	30023				
Property Address	1030 NE Orenco Station Parkway Hillsboro, OR 97124				
Description of Project/Service (Brief title of posting)	2 Emergency Lighting system Inverter replacements				
Project Start Date	8/1/2021	Project End Date	8/15/2021		
Community Contact	Brittany Rice	Contact Tel #	(503) 430-1616	Contact Email: BRice	@windsorcommunities.com
Vendor Qualifications (Licenses, Certificates, etc...)	licensed and bonded.				
Vendor Experience in local marketplace (Years in industry, number of similar past projects, etc...)	5yrs experience in industry				
Scope of work	Safe-off, demo, and removal of (1) 7.5kw and (1) 10kw lighting inverter. Provided replacement of equal capacity Meyers lighting inverter. New replacements have higher input current rating, so we have included upsizing the feed breakers and wire to the inverters.				

NOTE: The IMP – CalPERS Responsible Contract form & The IMP – CalPERS Neutrality Agreement form must be submitted for all contractors bidding on the Project/Service. These forms can be found on the intranet under Purchasing Forms.